



**Figure 1: DAMAGE IS PRESENT ON ALL SLOPES.**




**Figure 2: DAMAGE IS CONCENTRATED ON FIELDS & FOLLOWS A PATTERN.**




**Figure 3: SHINGLE TABS WITH DOUBLE CREASES.**



**Figure 4: TOTALLY, PARTIALLY AND DIAGONALLY TORN SHINGLE TABS.**



**Figure 5: CREASED SHINGLES THAT GOT REPAIRED ARE NOT SUSCEPTIBLE TO WIND DAMAGE.**



**Figure 6: REPORTED WIND SPEEDS AT THE SITE SHOULD CORRESPOND WITH FOUND DAMAGE.**